

PRODUCT DATA SHEET

NORGLASS LABORATORIES PTY.LTD.

A.B.N. 92 001 807 245

P.O. Box 312, Neutral Bay. NSW 2089 Australia

59 Moxon Road, Punchbowl NSW

Ph: 61 2 9708 2200 Email: techinfo@norglass.com.au

Web: norglass.com.au



NORCELLS

DESCRIPTION: A blended lightweight extender for Norglass epoxies.

USES: For filling and fairing surfaces.

SIZES: 1kg, 500g, 250g

PROPERTIES (at 20°C)

COLOUR: White

TOXICITY: Non-Hazardous

FINISH: N/A

COVERAGE: Varies according to Epoxy Resin mix.

DRYING TIME: N/A

RECOATING: N/A

POT LIFE: Subject to resin volume.

MIXING RATIO: Discretionary – Usually 1:1 mixing ratio by volume

THINNING: N/A

WEIGHT/LITRE: 100g

VOLUME SOLIDS: N/A

FLASH POINT:	N/A
CLEAN UP:	Norglass EPOXY THINNER
U.N. NUMBER:	N/A
TRANSPORTATION:	Non-Hazardous
PREPARATION:	Add NORCELLS to the base component and mix thoroughly before adding the hardener component. Spread the mix on a board or palette to reduce the thickness of the mix before applying to minimize heat development.
APPLICATION:	Apply to the surface with a squeegee, trowel or spatula. On vertical surfaces, the consistency should be made stiff enough to prevent sagging.
PRECAUTIONS:	Wear a mask and goggles whiles using. Wash hands thoroughly after handling. Only use in a well-ventilated area. Avoid inhaling its dust. Do not use in windy conditions. Keep out of reach of children
SPECIAL INSTRUCTIONS:	N/A
FIRST AID:	If in Eyes rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists get medical advice. If on Skin wash with plenty of soap and water. Take off contaminated clothing and wash before re-use. If skin irritation occurs get medical advice/attention. If Swallowed rinse mouth. Never give anything to the mouth of an unconscious person. If vomiting occurs, place victim face downwards, with the head turned to the side and lower than the hips to prevent vomit entering the lungs. If Inhaled remove person to fresh air. Remove contaminated clothing and loosen remaining clothing. Allow person to assume most comfortable position and keep warm. Keep at rest until fully recovered. Get medical advice if breathing becomes difficult Wear gloves, goggles and mask when incorporating.